



Confidential Home Inspection Report

Of Your New Home Panama City, FL 32404 Today's Date

Inspection ID 461234

By Cory Brookins Of Five Star Inspections P.O Box #0791 Lynn Haven, FL 32444 (850) 819-3388

A proud member of the Best Inspectors Network™

Building Description

	Description / Type	Address / Comments
Age (approximate)	15 years	Your New Home
Area (approximate)	1600 square feet	_
Building type	Single family, tri-level Single family, split level	-
	X Single family, ranch	
	See comments	
Construction	Not applicable	
	X Frame	
	Brick	
	See comments	
o Boardoni, 2 Barnoo		
3 Bedroom, 2 Bathroom	ding Description/ Commen	
	ghout this report indicating damage or ite	ems marked as needing repair may result in further damage or may
present a health or saf	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may
present a health or saf Client Informa	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may
Client Information	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may
Client Information Name Address	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may
Client Information Name Address Phone (home)	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may
Client Information Name Address Phone (home) Phone (work)	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may
Client Information Name Address Phone (home) Phone (work) Phone (cell)	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may
Client Information Name Address Phone (home) Phone (work)	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may
Client Information Name Address Phone (home) Phone (work) Phone (cell) Street address	ety hazard if not repaired.	ems marked as needing repair may result in further damage or may

Any report represents an impartial opinion of the physical condition of the named components below of the property from a limited visual inspection of those components and operating systems, which are readily visible and accessible on the day and at the time of the inspection.

Company can not be held liable for latent, concealed, non-visible, or obscured defects.
This is not a technically exhaustive inspection. A truly exhaustive inspection of a house and utility systems would require destructive tests and be absolutely time and cost prohibitive for the average homeowner/buyer.

This report is not a warranty or guarantee (expressed or implied) that the items are defect free, or that latent or concealed defects do not exist, may have existed in the past, or may exist or become evident in the future, or that the defects we have referenced in this report are the only defects that exist.

Weather at time of inspection

Temperature	Start Time	General Conditions
91° Fahrenheit	9:00	Clear

Grounds

	I = Inspected			ted	NI = Not Inspected NP = Not Present	R = Repair Needed	D = Defective
<u></u>	⊗ NI	⊗ NP	⋛	⊗ D	Item Comments	Condition	
X					Driveway and Side walks Concrete	Good	
X					Front yard Sod	Good	
×					Front porch Concrete	Good	
X					Side yards Sod	Good	
×					Back yard Sod	Good	
×			×		Trees and Shrubs	Fair	
X					Grade Properly slopes away from the home	Good	
×					Drainage and Sewers	Good	

Photos and Additional Comments

There are palm branches that are rubbing the shingles on the south side of the roof. These palm branches should be trimmed away from the home.



Roof

461234

		l = In	spec	ted	NI = Not Inspected	NP = Not Present	R = Repair Needed	D = Defective
<u></u>	№ NI	⊗ NP	℀ R	⊗ D	Item/ Comments		Condition	
X			×	X	Shingles Composite Asphalt/Fibe	rglass	Poor	
×			×	X	Decking OSB		Poor	
×					Flashings Galvanized Aluminum		Good	
×					Plumbing Vents		Good	
×					Ventilation Soffits, Ridge		Good	
		×			Gutters, downspouts			
×					Deck		Good	
		×			Skylights			

Photos and Additional Comments

The roof of the home is 17 years old and has deteriorated. The shingles are bowing and crumbling and there are multiple moisture stains in the roof decking. It is recommended that a licensed roofer be brought in to evaluate and replace the roof of the home.



Structure, Exterior, and Attachments

	I = Inspected			ted	NI = Not Inspected	NP = Not Present R	R = Repair Needed	D = Defective
3	⊗ NI	⊘ NP	⋛ R	⊗ D	Item		Condition	
×			×	X	Siding		Fair	
×					Fascia, Soffits Vinyl, Vinyl		Good	
×					Foundation Concrete Slab		Good	
×					Windows		Good	
×					Window screens		Good	
×					Water faucets		Good	
×					Doors		Good	
×					Trim Galvanized aluminum		Good	

Photos and Additional Comments

The stucco of the home has recently had cracks repaired and been painted. The majority of these repairs took place near the gable of the east wall where an expansion joint was never installed. However, new cracks have formed (most are on the east wall of the home) that need to be addressed. It is recommended that a stucco technician address the current cracks, and a plan of action be established for the prevention of further siding issues. **Cracked Stucco:**



Garage

	I = Inspected			ted	NI = Not Inspected NP = Not Present	R = Repair Needed	D = Defective
<u></u>	<mark>⊗</mark> NI	⊗ NP	⋛ R	& D	Item	Condition	
X					Siding Same as home	Good	
X					Fascia, Soffits, Trim Same as home	Good	
×					Foundation Concrete Slab	Good	
×					Electrical	Good	
×					Door to home 4" rise	Good	
X			×	X	Utility Door	Fair	
X					Garage Door Pressure reverse, electric eye	Good	
X					Walls	Good	

Photos and Additional Comments

There is wood rot in the bottom of the utility garage door trim. This wood rot should be cut out and replaced.



I = Inspected	NI = Not Inspected NP = Not Present	R = Repair Needed D = Defective
S NI NP R D	Item Comments	Condition
× 🗆 🗆 🗆	Access Garage, pull down stairs	Good
X	Insulation Fiberglass batts, sprayed cellulose, R-38	Good
X X	Moisture, Stains See "Roof"	Fair
	Truss Plates steel	Good
	Trusses Fink	Good
× 🗆 🗆 🗆	Ventilation Soffit, Ridge	Good
	Attic fan	
×□□□□	Attic baffles	Good

Photos and Additional Comments

Moisture Stains in Decking:



©1999-2007 MSI International, Inc. $B est I nspectors . N et^{TM}$

Bedrooms

461234

NI = Not Inspected NP = Not Present OK = Acceptable R = Repair Needed I = Inspected D = Defective Location/ Item R D Comment OK × X Bedroom 1 Doors Shut and lock X Bedroom 1 Ceiling Fan and light X Bedroom 1 Floor Oak X Bedroom 1 Windows Shut and lock X Bedroom 1 Walls X Bedroom 2 Doors Shut and lock X Bedroom 2 Ceiling Fan and light × Bedroom 2 Floor Carpet X Bedroom 2 Windows X Bedroom 2 Walls X Doors Bedroom 3 Shut and lock X Bedroom 3 Ceiling Fan and light X Bedroom 3 Floor Carpet X Bedroom 3 Windows Shut and lock × Bedroom 3 Walls Bedroom 4 Doors Bedroom 4 Ceiling Bedroom 4 Floor Bedroom 4 Windows Bedroom 4 Walls **Additional Comments** The lever for the window locking mechanism in the second bedroom has broken off. This prevents the lock from working. It is recommended that this lock be replaced.

Rooms

I = Inspected	NI = Not	Inspe	cted NP = Not Present	OK = Acceptable	R = Repair Needed	D = Defective
S NI NP	OK R	⊗ D	Location/ Comment	Item		
×	X		Foyer	Doors		
×□□	 		Foyer	Ceiling		
x	 		Foyer	Floor		
×□□	 		Foyer	Windows		
\times	x		Foyer	Walls		
			Living room	Doors		
×□□	 		Living room	Ceiling		
×□□	 		Living room	Floor		
×□□	 		Living room	Windows		
×□□	 		Living room	Walls		
			Dining Room	Doors		
×□□	 		Dining Room	Ceiling		
×□□	x		Dining Room	Floor		
×□□	x		Dining Room	Windows		
×□□	x		Dining room	Walls		
×□□	 		Smoke Detectors			
			Additional Comments No major defects or deficiencie	es observed		
			The major defects of deficiencies	observed.		
			·	·	·	

Bathrooms

No	I = Inspected		cted NP = Not Present	OK = Acceptable R = Repair Needed	D = Defective
Master bedroom	🗳 🔊 🛇	<u>₽</u> 🎇 🔇	Location/	Item	
X			Comment		
X		$\mathbf{x} \sqcup \mathbf{u}$		Electrical outlets	
Name					
Master bedroom				Toilet	
P-trap			<u> </u>	2	
X				Plumbing	
Master bedroom				Chause	
X			Master Deciroom	Silowei	
X	\square	\square	Master hedroom	Rath tub	
X			Madtor Boardon	Dairrido	
X	\square	\square	Bathroom 2	Electrical outlets	_
Name					
Name	$ x \square \square$	$ \mathbf{x} \square \square$	·	Toilet	
P-trap Bathroom 2			Secure		
X X Bathroom 2 Shower X X Bathroom 2 Bath tub X Bathroom 3 Electrical outlets X Bathroom 3 Toilet X Bathroom 3 Shower X Bathroom 3 Bathroom 3 Bathroom 3 Bath tub X Bathroom 4 Electrical outlets X Bathroom 4 Toilet X Bathroom 4 Plumbing X Bathroom 4 Shower X Bathroom 4 Bathroom 4 Bathroom 4 Bathroom 4 Bathroom 4	<u> </u>	X _ _	Bathroom 2	Plumbing	
X X Bathroom 2 Bath tub X Bathroom 3 Electrical outlets X Bathroom 3 Toilet X Bathroom 3 Plumbing X Bathroom 3 Shower X Bathroom 3 Bath tub X Bathroom 4 Electrical outlets X Bathroom 4 Toilet X Bathroom 4 Plumbing X Bathroom 4 Shower X Bathroom 4 Bathroom 4 Bathroom 4 Bathroom 4 Bathroom 4			P-trap		
		$\mathbf{X} \sqcup \mathbf{L}$	Bathroom 2	Shower	
		$\mathbf{X} \sqcup \mathbf{\Box}$	Bathroom 2	Bath tub	
			Bathroom 3	Electrical outlets	
			Dethers are 0	Teller	
			Bathroom 3	rollet	
			Bathroom 3	Plumbing	
Bathroom 3 Bath tub Bathroom 4 Electrical outlets Bathroom 4 Toilet Bathroom 4 Plumbing Bathroom 4 Shower Bathroom 4			<u>Battilooni o</u>	Tidifishing	
			Bathroom 3	Shower	_
Bathroom 4 Toilet Bathroom 4 Plumbing Bathroom 4 Shower Bathroom 4 Bath tub Additional Comments			Bathroom 3	Bath tub	
Bathroom 4 Toilet Bathroom 4 Plumbing Bathroom 4 Shower Bathroom 4 Bath tub Additional Comments					
Bathroom 4 Plumbing Bathroom 4 Shower Bathroom 4 Bath tub Additional Comments			Bathroom 4	Electrical outlets	
Bathroom 4 Plumbing Bathroom 4 Shower Bathroom 4 Bath tub Additional Comments					
Bathroom 4 Shower Bathroom 4 Bath tub Additional Comments			Bathroom 4	Toilet	
Bathroom 4 Shower Bathroom 4 Bath tub Additional Comments			-		
Bathroom 4 Bath tub Additional Comments			Bathroom 4	Plumbing	
Bathroom 4 Bath tub Additional Comments			- <u></u>		
Additional Comments			Bathroom 4	Shower	
Additional Comments			Rathroom 4	Rath tub	
			Datinooni 4	Butilido	
			Additional Comments		
				observed.	

I = In	spec	ted	NI =	Not	Inspe	ected NP = Not Present	OK = Acceptable	R = Repair Needed	D = Defective
\$	NI NI	NP	 OK	₩ R	⊗ D	Location/ Comment	Item	•	
		×				Kitchen	Door		
×			×			Kitchen	Walls		
×			×			Kitchen	Ceiling		
×			×			Kitchen	GFCI Electrica	al Outlets	
×			×			Kitchen	NON-GFCI EI	ectrical Outlets	
×			×			Kitchen	Lights		
×			×			Kitchen	Range		
		×				Kitchen	Refrigerator		
×			×			Kitchen	Microwave Ov	ven	
×			×			Kitchen	Dishwasher		
×			×			Kitchen	Exhaust fan		
×			×			Kitchen	Countertops		
×	П	\Box	×		$\overline{\Box}$	Kitchen	Sink		
×			×			Kitchen	Plumbing		
×	П		×						
	\Box					Kitchen	Cabinets		
		×				Kitchen	Windows		
×	Ш	Ш	×	Ш	Ш	Kitchen	Smoke Detect	tor	
×			×			Kitchen	Disposal		
		×				Kitchen	Trash compac	ctor	
		×				Kitchen	Water Filter		
						Additional Comments			
						No major defects or deficiencies of	bserved.		
	Ш		Ш	Ш	Ш				

Plumbing

	I = Inspected		ted	NI = Not Inspected NP = Not Preser	nt R = Repair Needed	D = Defective	
<u></u>	№ NI	⊗ NP	⋛	ॐ D	Item Comments	Condition	
X					Water Meter	Good	
×					Main Shut-off Valves	Good	
×					Water Heater State Select, 50 Gallons, Electric, Model #:E	Good S652DORTG, Serial #: G07 <i>l</i>	A016274
		×			Gas Meter		
		x [Soil Stack		
		× [Sump Pump		
×					Piping Copper, PVC	Good	
		×			Water Treatment		

Photos and Additional Comments

The home receives its water from a public utility. The water meter is located on the East edge of the property and is properly equipped with a shut-off valve. The home has adequate pressure and drainage to all faucets, and the water heater is properly working. There are no major defects or deficiencies to the home's plumbing.



Heating and Cooling

	I = Inspected			ted	NI = Not Inspected NP = Not Present	R = Repair Needed D = Defective
<u></u>	⊗ NI	⊘ NP	्र R	⊗ D	Item Comments	Condition
X					Heat Pump	Good
					Rheem, Model #: RHSA-HM3617JA, Serial #: M	O207 B1905
Ш	Ш	×	Ш	Ш	Flue piping	
X					Air conditioner	Good
					Rheem, Model #: RPNE-036JAZ, Serial #: 7348	M1907 10674
Ш	Ш	×	Ш	Ш	Supplemental heating equipment	
		×			Supplemental cooling equipment	
		×			Humidifier	
×					Gas lines, Valves	Good
					Copper	
×					Distribution	Good
					Flex Metal Duct	

Photos and Additional Comments

The home is heated and cooled from Rheem A/C and heat pump units. Both units fired upon a change to the thermostat, and both units operated within the proper temperature differential. There are no major defects or deficiencies to the home's heating and cooling units.



461234

Electrical

	I = Inspected				NI = Not Inspected NP = Not Present	R = Repair Needed	D = Defective
<u></u>	№ NI	⊘ NP	℀ R	ॐ D	Item Comments	Condition	
X			X		Subpanel	Fair	
					See Comments		
×					Main panel	Good	
			_	_	South exterior wall		
×					Main breaker, Main Disconnect	Good	
×	Ш	Ш	_	Ш	Made electrode - water line	Good	
×					Made electrode - ground rod	Good	
×				Ш	Branch circuits	Good	
					Romex		
	П	×			GFCI breakers		
		١٠٠١					
×					AFCI breakers	Good	

Photos and Additional Comments

The electrical supply to the home is via a public underground source. The main panel for the home is located on the south exterior wall and the subpanel is located in the garage. Both panels are equipped with the proper size breakers. The home's electrical supply is grounded and the distribution throughout the home is from romex wiring. There are two double tapped breakers in the subpanel of the home.

